




Date and Description	Image
<p>30/10 – 27/11/1953</p> <p>Earliest available aerial imagery. Site is comprised of vegetation without evidence of clearing.</p>	
<p>20/04-19/06/1985</p> <p>Clearing for sand mining operations commenced in southeastern corner.</p>	
<p>03/01-24/02/2000</p> <p>Clearing and sand mining has progressed to the centre and east. Landform has been reinstated in southeast corner.</p>	



Date and Description	Image
----------------------	-------

17-24/12/2005  
Clearing continues further north.



20/11/2011  
Clearing continues further northwest. Landform reinstated to the south. Vegetation has started to regrow in the south.



17-22/09/2015  
Clearing has affected majority of the Project Area excluding the centre.



Date and Description	Image
----------------------	-------

12/05-08/07/2018  
Maximum extent of clearing reached, vegetation continues to regrow in south and centre of the Project Area.



05-16/02/2025  
Current condition of the Project Area.

